

SECTION 3.10 - Each Journeyman shall be required to furnish a minimum kit of tools necessary to perform his classification of work. The following shall be considered a minimum tool list for a Journeyman Inside Wireman:

2 pr. channel lock type pliers	1 set spin tite wrenches - 3/16"
1 pr. 8" or 9" cutter pliers	5/16", 11/32", 3/8", 7/16"&1/2"
1 pr. 6" or 7" diagonal cutter pliers	1 set Allen wrenches, up to and including 3/8" size
1 pr. needle nose pliers	1 set wrenches; open end, box socket or adjustable to 1"
1 pipe wrench-14" or small chain tongs	1 wire skinning pocket knife
1 adjustable 10" wrench	1 level, 9" or 12"
1 screwdriver, stubby	1 tap wrench, up to 1/4"
1 screwdriver, 3" blade	1 pr. airplane shears, 10" straight cut
1 screwdriver, 5" blade	1 voltage tester-induction type (not neon or incandescent)
1 screwdriver, 8" blade	1 chalk line
1 Phillips screwdriver, size 1 & 2	1 flashlight (batteries furnished by Employer)
1 wood chisel - 3/4"	* 1 set of taps-#6/32, #8/32, #10/24, 1/4 - 20
2 cold chisels, 1/2 & 1"	1 center punch
1 hack saw frame, adjustable	1 plumb bob
* 1 key hole saw	1 claw hammer
1 folding rule - 6'	safe working shoes
1 tool box	
* 1 set of drills, 1/8", 5/32", 3/16" 7/32", 9/32", 3/8", #36, #29, #25, #7	
1 scratch awl	
1 combination square - 12"	
1 leather tool pouch	
pencils	

* Broken or worn cutting tools starred are to be replaced by Employer.

The Employer shall furnish all wrenches of any description, 16" or more in length, hack saw blades, cutting tools, bits, special tools of any kind and other necessary tools and equipment, including facilities for delivering Employers tools and materials to the job site. The Employer shall also provide a safe place for storage of all tools including the employees personal tools. Workmen shall be responsible for pick up and storing of the tools and/or equipment.

Workmen shall move personal tools, after 4:30 p.m., to next job site for the following day, if notified before 4:30 p.m.